

Premium Coastal SG Double Hung- Structural Performance Data

Product Style	Product ID	OP/ST	Configurations	Mull Type	DP Rating		WDMA	Max Tributary Width	Max Operating Frame Size	Max Pic/Tran Frame Size	Installation Type	Glass	Performance			Test Report #	FL #
					+	-							WZ3	WZ4	HVHZ		
Single Units																	
Double Hung	1105	OP	1 Wide	-	50	70	LC-PG50	-	47 1/2"x95 1/2"	-	Nailfin ----- -----	8.6mm PVB	Y	N	N	ESP020120P-1728.1	FL14939.8
Double Hung Transom	1110	STAT	1 Wide	-	55	70	CW-PG55	-	-	47 1/2"x41 1/2"	Nailfin Clips Screws	8.6mm PVB	Y	N	N	ESP020491P-1753	FL28127.6
Double Hung Picture	1108	STAT	1 Wide	-	55	70	CW-PG55	-	-	55 1/2"x95 1/2"	Nailfin Clips Screws	11.7mm SGP 11.7mm SGP HS	Y	N	N	ESP020513P-1754	FL28127.4
Mulled Combinations																	
Double Hungs	1105	OP/OP	2-3 wide	Tight mull	50	70	LC-PG50	47 1/2"	47 1/2"x95 1/2"	-	Nailfin ----- -----	See individual windows	Y	N	N	DH - ESP020120P-1728.1 Mullion - ESP020699P-1767	FL14939.8 FL14939.10
Double Hung w/Transom(s) Stacked Above and/or Below	1110 1105	STAT/OP	1W/2H or 1W/3H	Tight stack	55	70	LC-PG55	68 1/2"	47 1/2"x95 1/2"	47 1/2"x41 1/2"	Nailfin Clips Screws	See individual windows	Y	N	N	Transom - ESP020491P-1753 DH - ESP020120P-1728.1 Mullion - ESP024264P-2079.1	FL28445.3
Double Hung Mull'd Beside DH Picture	1105 1108	OP/STAT	2-3 wide	Tight mull with steel stiffner	55	70	LC-PG55	51 1/2"	47 1/2"x83 1/2"	55 1/2"x83 1/2"	Nailfin Clips Screws	See individual windows	Y	N	N	Picture - ESP020513P-1754 DH - ESP020120P-1728.1 Mullion - ESP020699P-1767	FL28127.3
Picture/Picture	1108	STAT/STAT	2-3 wide	Tight mull with steel stiffner	55	70	LC-PG55	55 1/2"	-	55 1/2"x83 1/2"	Nailfin Clips Screws	See individual windows	Y	N	N	Picture - ESP020513P-1754 Mullion - ESP02426P-2079.3	FL28127.5